

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	5522	((calibrate or rotate or rotating or adjustable or adjusting or taring or zero) near3 spring)	US-PGPUB	OR	OFF	2005/09/23 18:31
L2	793	1 and scale	US-PGPUB	OR	OFF	2005/09/23 18:32
L3	2948	((calibrate or adjustable or adjusting or taring or zero) near3 spring)	US-PGPUB	OR	OFF	2005/09/23 18:32
L4	487	3 and scale	US-PGPUB	OR	OFF	2005/09/23 18:32
L5	7017	weighing and scale	US-PGPUB	OR	OFF	2005/09/23 18:32
L6	66	3 and weighing	US-PGPUB	OR	OFF	2005/09/23 18:32
L7	1042	((adjustable or adjusting or taring or zero) near5 spring).clm.	US-PGPUB	OR	OFF	2005/09/23 18:33
L8	19	(((adjustable or adjusting or taring or zero) near5 spring) near10 (rotate or rotatable or turn) ).clm.	US-PGPUB	OR	OFF	2005/09/23 18:34